



Data transmission units, maximum number of measuring devices that can be connected: 2



Order data

Order number	498904 2
GTIN	2050001958754
Item class	49H

Description

Version:

For connection of measuring tools with Digimatic data outputs to a PC via a USB interface. The data can be loaded under software control, or using the data button on the measuring tool, or using an optional pedal switch.

Data transmission device for measuring tools with Digimatic and Opto-RS interfaces.

Supplied with:

USB data cable for connection to the PC.

Optional extras:

Foot switch No. 498903.

Adapter cable for connecting measuring tools with Opto-RS interface No. 498908, set for connecting RS232 to a PC including power supply unit and connecting cable.

Number of Digimatic inputs: 3

Opto-RS connection input: yes

Number of USB outputs: 1

Connection foot-switch: yes

Technical description

Number of USB outputs	1
-----------------------	---

Connection foot-switch	yes
Number of Digimatic inputs	3
Opto-RS connection input	yes
Type of product	Data transmission unit